



**RENAULT CLIO GRANDTOUR: 1NBE762**

Vinnumber:	<b>VF17RKJ0A53921329</b>	Versionname:	<b>1.5 ENERGY DCI 90 DYNAMIQUE</b>
First Registrationdate:	<b>11/01/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>77430</b>	Power Kw:	<b>66</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>NOT OK</b>	Parking lot:	<b>3515</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Windows electric F	Luggage cover
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**


	<b>195/55/16/92 MS LightMetal</b>			
Winter tyres:	Fr.L.	<b>Continental: 4 mm</b>	Fr.R.	<b>Continental: 4 mm</b>
	Re.L.	<b>Continental: 5 mm</b>	Re.R.	<b>Continental: 5 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	958,82
Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete)	232,06





Roof, Scratch(es), LI - Repair and paint (complete)	385,20
---	--------



Alloy rim R R polished, Scratch(es), Acceptable	0,00
---	------

*No pictures to display*

Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Interior, Worn, Acceptable	0,00
----------------------------	------



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	246,56
---	--------



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Maintenance, Maintenance, Execute	0,00
-----------------------------------	------

*No pictures to display*

Alloy rim F L polished, Scratch(es), Acceptable	0,00
---	------

*No pictures to display*

Wing R R, Dent(s), Acceptable	0,00
-------------------------------	------

*No pictures to display*

Windscreen, Stone chip(s), E - Replace	0,00
--	------



Rear window, Scratch(es), E - Replace	0,00
---------------------------------------	------

