


TOYOTA Grand Prius Plus: 1JSB647

Vinnumber:	JTDZS3EU603101959	Versionname:	GRAND PRIUS+ Hybrid Comfort 99PK Aut.
First Registrationdate:	11/02/2015	Fiscalpower:	
Expertise Mileage:	74538	Power Kw:	73
Bodytype:		Body color:	White
Gearbox:	Automatic	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Hybrid Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4514
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric
GPS storage	HD	Panoramic roof
GPS storage		Central consol F
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	
Head-up Display		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/96 H Steel			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1292,21
-------------------	---------

Wheel cover F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)	358,50
---	--------



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

366,35



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Wheel cover F L, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Rocker panel inner R R, Dent(s), LI - Repair and paint (complete)

115,56



Luggage space cover, Missing, E - Replace

240,00



Wheel cover R L, Scratch(es), Acceptable

0,00

No pictures to display