



**VOLKSWAGEN PASSAT VARIANT: 1LHP162**

|                                    |                          |              |                                    |
|------------------------------------|--------------------------|--------------|------------------------------------|
| Vinnumber:                         | <b>WVWZZZ3CZGE075035</b> | Versionname: | <b>2.0 TDI VARIANT COMFORTLINE</b> |
| First Registrationdate:            | <b>30/09/2015</b>        | Fiscalpower: |                                    |
| Expertise Mileage:                 | <b>79350</b>             | Power Kw:    | <b>110</b>                         |
| Bodytype:                          |                          | Body color:  | <b>Grey</b>                        |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                     |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>                   |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                          |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>4610</b>                        |
| Number of doors:                   | <b>5</b>                 |              |                                    |
| Number of seats:                   | <b>5</b>                 |              |                                    |
| Number head rests:                 | <b>5</b>                 |              |                                    |
| Rims summer:                       | <b>Aluminium</b>         |              |                                    |
| Category:                          | <b>Passenger Car</b>     |              |                                    |
| Oil level:                         | <b>OK</b>                |              |                                    |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                    |

**Options**

|                                |                              |                       |
|--------------------------------|------------------------------|-----------------------|
| Radio CD                       |                              | Central consol F      |
| GPS storage                    |                              | Luggage cover         |
| GPS storage                    | <b>SD</b>                    | Front parking sensors |
| Windows electric F             |                              | Rear parking sensors  |
| Windows electric R             |                              |                       |
| Cruise Control                 |                              |                       |
| Steering wheel multifunctional |                              |                       |
| Seats F heated                 |                              |                       |
| Radio multimedia               |                              |                       |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                       |
| Type of GPS                    | <b>GPS big screen color</b>  |                       |
| Type of Lining                 | <b>Lining fabrics</b>        |                       |
| Type of climate control        | <b>Autom climate control</b> |                       |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                  |       |                    |       |                    |
|----------------------------------|-------|--------------------|-------|--------------------|
| <b>215/60/16/99 H LightMetal</b> |       |                    |       |                    |
| Winter tyres:                    | Fr.L. | <b>Fulda: 5 mm</b> | Fr.R. | <b>Fulda: 5 mm</b> |
|                                  | Re.L. | <b>Fulda: 4 mm</b> | Re.R. | <b>Fulda: 4 mm</b> |

**Assistance equipment**




|  |            |            |            |
|--|------------|------------|------------|
| Repair kit                               | <b>Yes</b> | Compressor | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |            |            |
| Number of charging cables (rapid charge) | <b>0</b>   |            |            |

Total cost ex VAT 422,36

Wing R L, Dent(s), Acceptable 0,00

No pictures to display

Tailgate, Scratch(es), Acceptable 0,00

|  |  |        |
|--|--|--------|
| <i>No pictures to display</i>  |  |        |
| Bumper R, Scratch(es), Acceptable  |  | 0,00   |
| <i>No pictures to display</i>  |  |        |
| Wing R L, Scratch(es), Acceptable  |  | 0,00   |
| <i>No pictures to display</i>  |  |        |
| Alloy rim F L, Scratch(es), LI - Repair and paint (complete)                       |  | 95,00  |
|   |  |        |
| Door F R, Dent(s), Acceptable  |  | 0,00   |
| <i>No pictures to display</i>  |  |        |
| Rocker panel inner R L, Dent(s), LI - Repair and paint (complete)                  |  | 115,56 |
|   |  |        |
| Bumper F, Scratch(es), LI - Repair and paint (complete)                            |  | 211,80 |
|  |  |        |
| Wing F R, Scratch(es), Acceptable  |  | 0,00   |
| <i>No pictures to display</i>  |  |        |