



BMW 3 TOURING: 1LKU315

Vinnumber:	WBA8L71090K555385	Versionname:	2.0 316D (85KW) TOURING
First Registrationdate:	14/10/2015	Fiscalpower:	
Expertise Mileage:	168476	Power Kw:	85
Bodytype:		Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance	5000KM	Parking lot:	1405
Maintenance	NOT OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Rear parking sensors	
GPS storage		Type of Tow bar	No Tow bar
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 V LightMetal				
Summer tyres:	Fr.L.	Continental: 7 mm	Fr.R.	Continental: 7 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	2521,25
-------------------	----------------

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Wing R L, Scratch(es), Acceptable 0,00



Rear window, Scratch(es), E - Replace 0,00



Rear Panel Internal Lining, Scratch(es), Smart repair 110,64



Door R L, Scratch(es), Acceptable 0,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20



Door F R, Scratch(es), Acceptable 0,00



Bumper R, Dent(s) and scratch(es), Le - Replace and paint

651,00



Door R R, Scratch(es), Acceptable

0,00



Maintenance, Maintenance, Execute

0,00



Interior, Stain, Cleaning

75,00



Rearview mirror housing R, Broken, LI - Repair and paint (complete)

196,08



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80



Luggage space cover, Missing, E - Replace

240,00



Alloy rim R L, Scratch(es), Acceptable

0,00



Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

220,18

