



## VOLVO V60: 1NCT893

Vinnumber:	<b>YV1FW78C0G1316389</b>	Versionname:	<b>2.0 D2 GEARTRONIC KINETIC</b>
First Registrationdate:	<b>22/01/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>138008</b>	Power Kw:	<b>88</b>
Bodytype:		Body color:	<b>Blue</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>3119</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>215/55/16/92 MS LightMetal</b>			
Winter tyres:	Fr.L.	<b>Kleber: 4 mm</b>	Fr.R.	<b>Kleber: 4 mm</b>
	Re.L.	<b>Kleber: 5 mm</b>	Re.R.	<b>Kleber: 5 mm</b>

## Assistance equipment

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>1147,85</b>
Door F L, Dent(s), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Rear window, Scratch(es), E - Replace	<b>0,00</b>



Roof, Chemical pollution, LI - Repair and paint (complete)

481,50



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R L, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Door F R, Dent(s), PDR - Paintless dent repair

63,00



Bonnet, Scratch(es), Acceptable

0,00

No pictures to display

Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Windscreen, Scratch(es), E - Replace

0,00

