



VOLKSWAGEN Touran: 1JFN583

Vinnumber:	WVGZZZ1TZFW029872	Versionname:	TOURAN Highline BMT St&St 7pl.105PK
First Registrationdate:	4/12/2014	Fiscalpower:	
Expertise Mileage:	118940	Power Kw:	77
Bodytype:	Hatchback	Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1724
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Seats F heated	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control
	No Tow bar

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	967,60
-------------------	--------

Door R R, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Rear window, Scratch(es), Acceptable	0,00
--------------------------------------	------

No pictures to display

Rocker panel inner R R, Dent(s), Acceptable	0,00
---	------

<i>No pictures to display</i>		
Door R L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Tailgate, Dent(s), LI - Repair and paint (complete)		301,68
Wing R R, Dent(s), Acceptable		0,00
<i>No pictures to display</i>		
Wing F L, Dent(s), Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim R L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Backrest cover R R, Hole, Smart repair		64,32
Bumper F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)		95,00
Engine protective plate, Hole, E - Replace		104,80
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)		95,00
Bumper R, Scratch(es), LI - Repair and paint (complete)		211,80
Door F R, Dent(s), Acceptable		0,00
<i>No pictures to display</i>		

Backrest cover R R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Trunk lid covering R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Door F L, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display