



PEUGEOT Boxer 335: 1DVQ043

Vinnumber:	VF3YUMFC12274313	Versionname:	BOXER 335 B/F LWB L3H2 FAP 150PK
First Registrationdate:	11/09/2012	Fiscalpower:	
Expertise Mileage:	170099	Power Kw:	110
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV21
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Rear parking sensors	
Steering wheel multifunctional	Type of Tow bar	No Tow bar
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	No GPS	
Type of Lining	Lining artificial leather	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/70/15/107 S Steel			
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2602,07
Door moulding Lower F R, Missing, E - Replace	91,50



Ignition key, Missing, E - Replace 150,00

No pictures to display

Bumper F R, Scratch(es), Smart repair 110,64



Trunk door R R, Deformed / Strained, LI - Repair and paint (partial) 211,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 231,15



Wheel cover R R, Broken, E - Replace 22,50



Glove box cover, Crack, E - Replace 228,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Central pillar R, Dent(s) and scratch(es), It - Spot repair 115,56



Sliding door R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 165,13



Armrest F Mid, Worn, Acceptable 0,00

No pictures to display

Front end, Scratch(es), It - Spot repair 115,56



Bumper corner R R, Dent(s) and scratch(es), E - Replace 95,00



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 231,15



Bumper corner R L, Dent(s) and scratch(es), E - Replace	95,00
---	-------



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)	232,88
---	--------



Seat cover F L, Worn, Acceptable	0,00
----------------------------------	------

No pictures to display

Bonnet, Dent(s), Acceptable	0,00
-----------------------------	------

No pictures to display

Protection plate M, Hole, E - Replace	35,00
---------------------------------------	-------



Sidewall FL (LCV), Dent(s) and scratch(es), LI - Repair and paint (complete)	472,00
--	--------

