



AUDI A4: 1ELV271

Vinnumber:	WAUZZF4XGA034606	Versionname:	
First Registrationdate:	27/09/2016	Fiscalpower:	
Expertise Mileage:	112917	Power Kw:	110
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	4129
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage		Rear parking sensors
GPS storage	SD	
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Type of headlighting	Headlighting LED	
Type of GPS	GPS big screen color	
Type of Lining	Lining semi-leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	245/40/18/92 MS LightMetal			
Winter tyres:	Fr.L.	Other: 3 mm	Fr.R.	Other: 3 mm
	Re.L.	Other: 4 mm	Re.R.	Other: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	2082,84
Certificate Of Conformity, Missing, E - Replace	150,00
<i>No pictures to display</i>	
Protection plate M, Deformed / Strained, E - Replace	62,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

369,84



Sill outer R, Scratch(es), LI - Repair and paint (complete)

372,60



Maintenance, Maintenance, Execute

0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Door F R, Scratch(es), LI - Repair and paint (complete)

382,02



Door R R, Scratch(es), LI - Repair and paint (complete)

382,02



Outer door handle F R, Scratch(es), LI - Repair and paint (complete)

115,56



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Windscreen, Stone chip(s), Windscreen repair

58,80

