



**BMW 1 HATCH: FA5860**

Vinnumber:	<b>WBA1C71020P840806</b>	Versionname:	<b>2.0 116D (85KW)</b>
First Registrationdate:	<b>1/01/2000</b>	Fiscalpower:	
Expertise Mileage:	<b>169508</b>	Power Kw:	<b>85</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>1412</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>HD</b>	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	<b>No Tow bar</b>
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/55/16/91 H LightMetal</b>				
Winter tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

**Assistance equipment**

Repair kit	<b>No</b>	Compressor	<b>No</b>
------------	-----------	------------	-----------

Total cost ex VAT	<b>549,73</b>
-------------------	---------------

Bumper grille F R, Broken, E - Replace	<b>32,40</b>
--	--------------



Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Bumper F, Deformed / Strained, LI - Repair and paint (complete)	211,80
---	--------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Tyre repair kit, Missing, E - Replace	210,53
---------------------------------------	--------

