



BMW 3: 1JSE599			
Vinnumber:	WBA3K910X0F912879	Versionname:	3 TOURING 316dA 116PK Aut.
First Registrationdate:	12/02/2015	Fiscalpower:	
Expertise Mileage:	163714	Power Kw:	85
Bodytype:		Body color:	White
Gearbox:	Automatic	Paint type:	Opaque
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2125
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	NOT OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	205/60/16/96 H LightMetal			
Winter tyres:	Fr.L.	Pirelli: 4 mm	Fr.R.	Pirelli: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1226,20
Door R R, Dent(s), PDR - Paintless dent repair	82,80



Windscreen, Stone chip(s), Windscreen repair 0,00



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Mirror side blinker R, Broken, E - Replace 30,00



Bumper moulding F, Broken, E - Replace 109,60



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Grill frame, Missing, E - Replace 98,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Bonnet, Dent(s), PDR - Paintless dent repair 63,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 356,20



Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Dent(s), PDR - Paintless dent repair

63,00

