



**MINI : 1PEP148**

Vinnumber:	<b>WMWXN110703B51839</b>	Versionname:	<b>1.5 ONE D</b>
First Registrationdate:	<b>17/06/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>52932</b>	Power Kw:	<b>70</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>4809</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>3</b>		
Number of seats:	<b>4</b>		
Number head rests:	<b>4</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Windows electric F	Luggage cover
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>175/65/15/92 H LightMetal</b>				
Summer tyres:	Fr.L.	<b>Hankook: 4 mm</b>	Fr.R.	<b>Hankook: 4 mm</b>
	Re.L.	<b>Hankook: 5 mm</b>	Re.R.	<b>Hankook: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT 1008,34

Roof, Chemical polution, LI - Repair and paint (complete) 481,50





Bonnet, Dent(s), Acceptable	0,00
-----------------------------	------

No pictures to display

Wing moulding F R, Scratch(es), E - Replace	14,40
---	-------



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Bumper F, Scratch(es), Smart repair	110,64
-------------------------------------	--------



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

