


RENAULT MEGANE GRANDTOUR: 1RTZ149

Vinnumber:	VF1RFB00257244974	Versionname:	Energy dCi 110 Bose Edition
First Registrationdate:	1/03/2017	Fiscalpower:	
Expertise Mileage:	162341	Power Kw:	81
Bodytype:		Body color:	Red
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	1508
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Sun Roof electric
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Seats F heated	Rear parking sensors
Radio multimedia	
Type of headlighting	Headlighting LED
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/50/17/92 MS LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1020,68
Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)			95,00



Luggage space cover, Missing, E - Replace

240,00



Tyre R L, Deformed / Strained, E - Replace

132,00



Tailgate, Scratch(es), LI - Repair and paint (complete)

301,68



Rearview mirror housing L, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Engine protective plate, Deformed / Strained, E - Replace

62,00



Wing R L, Repaired, Acceptable

0,00

No pictures to display