



VOLKSWAGEN GOLF VARIANT: 1RAG643

| | | | |
|------------------------------------|--------------------------|--------------|------------------------------|
| Vinnumber: | VVWZZZAUZHP529477 | Versionname: | 1.6 TDI 81KW HIGHLINE |
| First Registrationdate: | 26/10/2016 | Fiscalpower: | |
| Expertise Mileage: | 92861 | Power Kw: | 81 |
| Bodytype: | | Body color: | Black |
| Gearbox: | MAN 5 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OK | Parking lot: | 2324 |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|------------------------------|
| Radio CD | Central consol F |
| Windows electric F | Luggage cover |
| Windows electric R | Front parking sensors |
| Cruise Control | Rear parking sensors |
| Steering wheel multifunctional | |
| Type of headlighting | Headlighting LED |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining fabrics |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|-----------------------------------|-----------------------|-------|-----------------------|
| | 225/45/17/92 MS LightMetal | | | |
| Winter tyres: | Fr.L. | Michelin: 4 mm | Fr.R. | Michelin: 4 mm |
| | Re.L. | Michelin: 5 mm | Re.R. | Michelin: 5 mm |

Assistance equipment

| | | | |
|-----------------------|------------|------|------------|
| Emergency spare wheel | Yes | Jack | Yes |
|-----------------------|------------|------|------------|

| | |
|---|---------------|
| Total cost ex VAT | 671,50 |
| Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) | 95,00 |



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Roof, Chemical polution, LI - Repair and paint (complete)

481,50

