



**BMW 1 HATCH: 1JKX462**

Vinnumber:	<b>WBA1C11010P531776</b>	Versionname:	<b>2.0 118D (100KW)</b>
First Registrationdate:	<b>13/01/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>125116</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>2528</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Type of headlighting	<b>Headlighting Xenon</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining artificial leather</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>245/35/18/92 MS LightMetal</b>			
Winter tyres:	Fr.L.	<b>Pirelli: 4 mm</b>	Fr.R.	<b>Pirelli: 4 mm</b>
	Re.L.	<b>Pirelli: 5 mm</b>	Re.R.	<b>Pirelli: 5 mm</b>

**Assistance equipment**

	Runflat	<b>Yes</b>
--	---------	------------

Total cost ex VAT	998,00
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00





Wing R L, Bad repair, LI - Repair and paint (complete)

0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Protection plate M, Deformed / Strained, E - Replace

62,00



Bumper R, Dent(s) and scratch(es), Le - Replace and paint

651,00



Door R L, Bad repair, LI - Repair and paint (complete)

0,00



Alloy rim R L, Scratch(es), Acceptable

0,00

*No pictures to display*

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00

