



AUDI A4: 1KLH820

Vinnumber:	WAUZZZ8K2FN042086	Versionname:	2.0 TDI ULTRA 100KW
First Registrationdate:	27/05/2015	Fiscalpower:	
Expertise Mileage:	143460	Power Kw:	100
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	49 DAGEN	Parking lot:	3829
Maintenance:	5800		
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	CD	Front parking sensors	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection



Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 H LightMetal				
Winter tyres:	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			112,40
Bumper F, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Door F L, Scratch(es), Acceptable			0,00

<i>No pictures to display</i>		
Outer backrest protection L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door F R, Dent(s), Acceptable		0,00
<i>No pictures to display</i>		
Bumper R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Tires, Not original part, Acceptable		0,00
<i>No pictures to display</i>		
Bumper grille F R, Broken, E - Replace		32,40
		
Wing R L, Dent(s), Acceptable		0,00
<i>No pictures to display</i>		
Door R L, Dent(s), Acceptable		0,00
<i>No pictures to display</i>		
Rear bulkhead lining, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Shutter / cover, Crack, E - Replace		80,00
		
Wing R R, Dent(s), Acceptable		0,00
<i>No pictures to display</i>		