



**FORD C-MAX: 1JTK301**

|                                   |                          |              |                                      |
|-----------------------------------|--------------------------|--------------|--------------------------------------|
| Vinnumber:                        | <b>WF0JXXGCBJEG64945</b> | Versionname: | <b>1.6 TDCI 85KW S/S TREND STYLE</b> |
| First Registrationdate:           | <b>20/02/2015</b>        | Fiscalpower: |                                      |
| Expertise Mileage:                | <b>105169</b>            | Power Kw:    | <b>85</b>                            |
| Bodytype:                         |                          | Body color:  | <b>Black</b>                         |
| Gearbox:                          | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                       |
| Transmission:                     | <b>Front</b>             | Rims summer: | <b>Aluminium</b>                     |
| Fueltype:                         | <b>Diesel</b>            | Oil level:   | <b>OK</b>                            |
| Maintenance                       | <b>PLUS 14871 KM</b>     | Parking lot: | <b>3524</b>                          |
| Maintenance                       | <b>OK</b>                |              |                                      |
| Battery functioning               | <b>Yes</b>               |              |                                      |
| Number of doors                   | <b>5</b>                 |              |                                      |
| Number of seats                   | <b>5</b>                 |              |                                      |
| Number head rests                 | <b>5</b>                 |              |                                      |
| Rims summer                       | <b>Aluminium</b>         |              |                                      |
| Category                          | <b>Passenger Car</b>     |              |                                      |
| Oil level                         | <b>OK</b>                |              |                                      |
| Registration Certificate Car (BE) | <b>Yes</b>               |              |                                      |

**Options**

|                                |                               |                      |                   |
|--------------------------------|-------------------------------|----------------------|-------------------|
| Radio CD                       |                               | Central consol F     |                   |
| GPS storage                    | <b>SD</b>                     | Luggage cover        |                   |
| GPS storage                    |                               | Rear parking sensors |                   |
| Windows electric F             |                               | Type of Tow bar      | <b>No Tow bar</b> |
| Windows electric R             |                               |                      |                   |
| Cruise Control                 |                               |                      |                   |
| Steering wheel multifunctional |                               |                      |                   |
| Type of headlighting           | <b>Headlighting Halogen</b>   |                      |                   |
| Type of GPS                    | <b>GPS big screen color</b>   |                      |                   |
| Type of Lining                 | <b>Lining fabrics</b>         |                      |                   |
| Type of climate control        | <b>Manual climate control</b> |                      |                   |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                  |       |                     |       |                     |
|----------------------------------|-------|---------------------|-------|---------------------|
| <b>215/55/16/93 H LightMetal</b> |       |                     |       |                     |
| Winter tyres:                    | Fr.L. | <b>Kleber: 5 mm</b> | Fr.R. | <b>Kleber: 5 mm</b> |
|                                  | Re.L. | <b>Kleber: 6 mm</b> | Re.R. | <b>Kleber: 6 mm</b> |

**Assistance equipment**

|                       |            |      |            |
|-----------------------|------------|------|------------|
| Emergency spare wheel | <b>Yes</b> | Jack | <b>Yes</b> |
|-----------------------|------------|------|------------|

|                   |               |
|-------------------|---------------|
| Total cost ex VAT | <b>271,80</b> |
|-------------------|---------------|

|                                   |             |
|-----------------------------------|-------------|
| Door R L, Scratch(es), Acceptable | <b>0,00</b> |
|-----------------------------------|-------------|



Boot cover, Damaged, E - Replace

50,00



Wing R L, Dent(s), Acceptable

0,00



Interior, Stain, Cleaning

100,00



Brand badge R, Chemical pollution, Acceptable

0,00



Maintenance book, Missing, E - Replace

0,00



Bumper R, Scratch(es), Acceptable

0,00



Door R R, Dent(s), PDR - Paintless dent repair

63,00



Door F L, Scratch(es), Acceptable

0,00

Door F L, Scratch(es), Acceptable

0,00



Wing R R, Dent(s), Acceptable

0,00



Windscreen, Stone chip(s), Windscreen repair

58,80



Alloy rim F R, Scratch(es), Acceptable

0,00



Floor covering F L, Hole, Acceptable

0,00

