



VOLVO V40: 1JRX197

Vinnumber:	YV1MV5151F2231483	Versionname:	2.0 D3 KINETIC
First Registrationdate:	10/02/2015	Fiscalpower:	
Expertise Mileage:	153324	Power Kw:	110
Bodytype:		Body color:	Red
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	1425
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	Tow bar fixed
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/92 MS LightMetal			
Winter tyres:	Fr.L.	Other: 4 mm	Fr.R.	Other: 4 mm
	Re.L.	Other: 5 mm	Re.R.	Other: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			260,00
Ignition key, Missing, E - Replace			150,00
<i>No pictures to display</i>			
Rear window, Scratch(es), E - Replace			0,00



Quarter light F R, Missing, E - Replace

15,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper F, Scratch(es), Acceptable

0,00

No pictures to display

Windscreen, Crack, E - Replace

0,00

