



VOLVO XC90: 1THN821

Vinnumber:	YV1LFBABDJ1338079	Versionname:	2.0 T8 4WD Geartronic Inscription 7PL
First Registrationdate:	9/11/2017	Fiscalpower:	
Expertise Mileage:	125519	Power Kw:	300
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Hybrid Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4116
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	HD	Seats electric F L
GPS storage		Seats electric F R
Windows electric F		Sun Roof electric
Windows electric R		Panoramic roof
Cruise Control		Central consol F
Steering wheel multifunctional		Luggage cover
Seats F heated		Front parking sensors
Radio multimedia		Rear parking sensors
Type of headlighting	Headlighting LED	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	
Level control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	NOT OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	275/45/20/110 V LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 2 mm	Fr.R.	Uniroyal: 2 mm
	Re.L.	Uniroyal: 3 mm	Re.R.	Uniroyal: 3 mm

Assistance equipment

Number of charging cables (normal)	1
Number of charging cables (rapid charge)	1

Total cost ex VAT	0,00
Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)	0,00



Roof pillar L, Dent(s), PDR - Paintless dent repair

0,00



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)

0,00



Bumper F, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R L polished, Scratch(es), Acceptable

0,00

No pictures to display

Ignition key, Missing, E - Replace

0,00



Bonnet, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

0,00

