



BMW 1 HATCH: 1LUE168

Vinnumber:	WBA1V71040V620122	Versionname:	1.5 116D (85KW)
First Registrationdate:	7/12/2015	Fiscalpower:	
Expertise Mileage:	81642	Power Kw:	85
Bodytype:		Body color:	Brown
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	7000KM OF 2-21	Parking lot:	3810
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Alarm			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment

Repair kit	No	Compressor	No
Total cost ex VAT			622,01
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)			95,00



Tyre repair kit, Missing, E - Replace 210,53



Bumper grille F L, Broken, E - Replace 32,40



Wing R L, Dent(s), Acceptable 0,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Dent(s) and scratch(es), Acceptable 0,00



Compressor, Missing, E - Replace 0,00



Rear wiper blade, Tear, E - Replace 31,08



Tyre R R, Tear, Acceptable 0,00



Interior, Worn, Acceptable

0,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Door frame R R, Scratch(es), 67 - Polish

0,00



Wing R R, Dent(s), PDR - Paintless dent repair

63,00

