



AUDI A6: 1NSX510

Vinnumber:	WAUZZZ4GXGN151463	Versionname:	2.0 TDI ULTRA 100KW S TRONIC
First Registrationdate:	19/04/2016	Fiscalpower:	
Expertise Mileage:	177891	Power Kw:	100
Bodytype:	Berline	Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OVER 14200 KM	Parking lot:	4112
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Front parking sensors	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar removable
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/60/16/98 H LightMetal				
Winter tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------


Total cost ex VAT	1496,93
-------------------	----------------

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

302,16



Wing R L, Scratch(es), LI - Repair and paint (complete)

369,84



Bonnet, Stone chip(s), Acceptable

0,00

No pictures to display

Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

312,21



Wing F R, Scratch(es), It - Spot repair

0,00



Rear bulkhead lining, Scratch(es), Acceptable 0,00

No pictures to display

Sill outer L, Scratch(es), It - Spot repair 115,56



Floor covering F L, Damaged, Acceptable 0,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 302,16

