



**BMW 3 TOURING: 1JSX650**

Vinnumber:	<b>WBA3K91020F937503</b>	Versionname:	<b>2.0 316D (85KW) TOURING</b>
First Registrationdate:	<b>17/02/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>168351</b>	Power Kw:	<b>85</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>2102</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Rear parking sensors
Type of headlighting	<b>Headlighting Xenon</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining artificial leather</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/55/16/92 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Firestone: 4 mm</b>	Fr.R.	<b>Firestone: 4 mm</b>
	Re.L.	<b>Firestone: 5 mm</b>	Re.R.	<b>Firestone: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>963,98</b>
-------------------	---------------

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	<b>95,00</b>
--	--------------



Wing R L, Bad repair, LI - Repair and paint (complete)

0,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Seat cover F L, Damaged, Acceptable

0,00



Rocker panel inner F L, Dent(s), LI - Repair and paint (complete)

115,56



Rocker panel inner F R, Dent(s), LI - Repair and paint (complete)

115,56



Bumper R, Scratch(es), Acceptable

0,00

*No pictures to display*

Rocker panel inner R R, Dent(s), LI - Repair and paint (complete)

115,56



Sill outer R, Scratch(es), LI - Repair and paint (complete)

310,50

