


MERCEDES A: 1GMZ864

Vinnumber:	WDD1760121J216069	Versionname:	A 180 CDI BE 109PK
First Registrationdate:	14/03/2014	Fiscalpower:	
Expertise Mileage:	74454	Power Kw:	80
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	1233
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining semi-artificial leather
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/17/92 H LightMetal			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	385,08
-------------------	--------

Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Maintenance, Maintenance, Execute	0,00
-----------------------------------	------

No pictures to display

Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
---	--------

