



|                                    |                          |              |                               |
|------------------------------------|--------------------------|--------------|-------------------------------|
| <b>BMW 5: 1JKG322</b>              |                          |              |                               |
| Vinnumber:                         | <b>WBA5E51060G056838</b> | Versionname: | <b>5 BER 520dA 163PK Aut.</b> |
| First Registrationdate:            | <b>9/01/2015</b>         | Fiscalpower: |                               |
| Expertise Mileage:                 | <b>157284</b>            | Power Kw:    | <b>120</b>                    |
| Bodytype:                          |                          | Body color:  | <b>Grey</b>                   |
| Gearbox:                           | <b>Automatic</b>         | Paint type:  | <b>Metalic</b>                |
| Transmission:                      | <b>Back</b>              | Rims summer: | <b>Aluminium</b>              |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                     |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>3502</b>                   |
| Number of doors:                   | <b>4</b>                 |              |                               |
| Number of seats:                   | <b>5</b>                 |              |                               |
| Number head rests:                 | <b>5</b>                 |              |                               |
| Rims summer:                       | <b>Aluminium</b>         |              |                               |
| Category:                          | <b>Passenger Car</b>     |              |                               |
| Oil level:                         | <b>OK</b>                |              |                               |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                               |

|                                |                              |                       |                   |
|--------------------------------|------------------------------|-----------------------|-------------------|
| <b>Options</b>                 |                              |                       |                   |
| Radio CD                       |                              | Seats electric F L    |                   |
| GPS storage                    |                              | Seats electric F R    |                   |
| GPS storage                    | <b>HD</b>                    | Central consol F      |                   |
| Windows electric F             |                              | Front parking sensors |                   |
| Windows electric R             |                              | Rear parking sensors  |                   |
| Cruise Control                 |                              | Type of Tow bar       | <b>No Tow bar</b> |
| Steering wheel multifunctional |                              |                       |                   |
| Seats F heated                 |                              |                       |                   |
| Radio multimedia               |                              |                       |                   |
| Type of headlighting           | <b>Headlighting Xenon</b>    |                       |                   |
| Type of GPS                    | <b>GPS big screen color</b>  |                       |                   |
| Type of Lining                 | <b>Lining leather</b>        |                       |                   |
| Type of climate control        | <b>Autom climate control</b> |                       |                   |

|                                     |           |                     |            |
|-------------------------------------|-----------|---------------------|------------|
| <b>Limited Technical Inspection</b> |           |                     |            |
| Airco functioning                   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile                  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position                       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime                 | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass                        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake                           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                                     |           | Lighting            | <b>OK</b>  |
|                                     |           | Wiperblades         | <b>OK</b>  |

|                       |                                   |                       |       |                       |
|-----------------------|-----------------------------------|-----------------------|-------|-----------------------|
| <b>Degree of wear</b> |                                   |                       |       |                       |
|                       | <b>225/55/17/101 V LightMetal</b> |                       |       |                       |
| Winter tyres:         | Fr.L.                             | <b>Uniroyal: 4 mm</b> | Fr.R. | <b>Uniroyal: 4 mm</b> |
|                       | Re.L.                             | <b>Uniroyal: 4 mm</b> | Re.R. | <b>Uniroyal: 4 mm</b> |

|  |            |            |              |
|--|------------|------------|--------------|
| <b>Assistance equipment</b>                                  |            |            |              |
| Repair kit   | <b>Yes</b> | Compressor | <b>Yes</b>   |
| Total cost ex VAT  |            |            | <b>95,00</b> |
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) |            |            | <b>95,00</b> |



|                                   |      |
|-----------------------------------|------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i>     |      |
| Bumper F, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i>     |      |