



**FORD TRANSIT CONNECT: GR1108**

Vinnumber:	<b>WF0RXXWPGRFC77426</b>	Versionname:	<b>1.6 TDCI 86KW (T220) TREND</b>
First Registrationdate:	<b>1/03/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>1</b>	Power Kw:	<b>86</b>
Bodytype:		Body color:	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>NOT OK</b>
Battery functioning:	<b>No</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>NOT OK</b>		
Registration Certificate Car (BE):	<b>No</b>		

**Options**

Radio CD	
Windows electric F	
Steering wheel multifunctional	
Type of GPS:	<b>No GPS</b>
Type of Lining:	<b>Lining fabrics</b>
Type of climate control:	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>NOT OK</b>	Battery functioning	<b>No</b>
Tires wear profile	<b>OK</b>	Power steering	<b>No</b>
Idle position	<b>NOT OK</b>	Sound engine	<b>NOT OK</b>
Engine startingtime	<b>NOT OK</b>	Clutch test	<b>NOT OK</b>
Exhaust gass	<b>NOT OK</b>	Wiper fluid level	<b>NOT OK</b>
Handbrake	<b>NOT OK</b>	Transmission	<b>NOT OK</b>
		Lighting	<b>NOT OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/60/16/94 H Steel</b>				
Winter tyres:	Fr.L.	<b>Continental: 6 mm</b>	Fr.R.	<b>Continental: 6 mm</b>
	Re.L.	<b>Michelin: 6 mm</b>	Re.R.	<b>Michelin: 6 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Total cost ex VAT			<b>1625,91</b>
Wheel cover R L, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Bodywork, Not original part, P - Check			<b>0,00</b>



Rearview mirror R complete, Broken, Le - Replace and paint



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 423,15



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R R, Scratch(es), Acceptable 0,00

No pictures to display

Trunk door R L, Dent(s), PDR - Paintless dent repair 63,00



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Dirty, Cleaning 150,00



Ignition key, Missing, E - Replace 300,00



Certificate Of Conformity, Missing, E - Replace 150,00



Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	286,76
---	--------



Wheel cover F L, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*

Wheel cover F R, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*