



FORD S-MAX: 1RKD803

Vinnumber:	WF0JXXWPCJGS08198	Versionname:	2.0 TDCi 110kW S/S PS Titanium
First Registrationdate:	10/01/2017	Fiscalpower:	
Expertise Mileage:	161212	Power Kw:	110
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2502
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK




















Degree of wear

	225/55/16/92 MS LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 4 mm	Fr.R.	Uniroyal: 4 mm
	Re.L.	Uniroyal: 5 mm	Re.R.	Uniroyal: 5 mm

Assistance equipment

Total cost ex VAT	1449,15
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00



Rearview mirror housing L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
 	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
 	
Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)	211,80
  	
	
Door R L, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Rearview mirror glass L, Broken, E - Replace	18,00
 	
Ignition key, Worn, E - Replace	0,00
 	
Door R R, Scratch(es), LI - Repair and paint (complete)	318,35
 	
Rear window, Scratch(es), E - Replace	0,00
 	
Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)	211,80
  	
Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	404,20

