



FORD Transit Custom: 1JEG822

Vinnumber:	WFOZXXTTGZER12482	Versionname:	TRANS.CUSTOM B/F2C 290L LWB Trend 100PK
First Registrationdate:	25/11/2014	Fiscalpower:	
Expertise Mileage:	183919	Power Kw:	74
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3123
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	6		
Number head rests:	6		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	No GPS
Type of Lining	Lining fabrics
Type of climate control	Manual climate control
	Tow bar fixed

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/65/15/104 T Steel				
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	2779,35
-------------------	---------

Bumper moulding F M, Scratch(es), E - Replace	10,80
---	-------



Bumper F, Broken, Le - Replace and paint



Rearlight L, Broken, E - Replace

91,50



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

238,76



Wing R R, Scratch(es), LI - Repair and paint (complete)

231,15



Wheel cover F R, Scratch(es), Acceptable

0,00

No pictures to display

Tyre F R, Tear, E - Replace

105,00



Headrest F R, Missing, E - Replace

45,00



Bumper moulding R L, Broken, E - Replace

10,80



Wheel cover R R, Broken, E - Replace

22,50



Rearview mirror housing R, Broken, E - Replace

115,56



Door R R, Deformed / Strained, LI - Repair and paint (complete)

238,76



Wing R L, Deformed / Strained, Le - Replace and paint

983,63



Bumper moulding R R, Scratch(es), Smart repair

110,64

