



**MERCEDES C BERLINE: 1NAC419**

Vinnumber:	<b>WDD2050371R137695</b>	Versionname:	<b>1.6 C 200 D AVANTGARDE</b>
First Registrationdate:	<b>4/01/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>153871</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Blue</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>4110</b>
Maintenance:	<b>250 DAGEN</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>4</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Sun Roof electric	
GPS storage	<b>SD</b>	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	<b>No Tow bar</b>
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	<b>Headlighting LED</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>225/50/17/98 H LightMetal</b>				
Winter tyres:	Fr.L.	<b>Pirelli: 6 mm</b>	Fr.R.	<b>Pirelli: 6 mm</b>
	Re.L.	<b>Uniroyal: 8 mm</b>	Re.R.	<b>Uniroyal: 8 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT 413,35

Door F R, Scratch(es), Acceptable 0,00




Door R L, Scratch(es), LI - Repair and paint (complete)

318,35



Tailgate, Scratch(es), Acceptable

0,00



Wing F L, Repaired, P - Check

0,00



Ignition key, Not functioning (well), Acceptable

0,00



Wing R R, Scratch(es), Acceptable

0,00



Bonnet, Dent(s), Acceptable

0,00



Tailgate, Not original part, Sticker removal

0,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Roof, Dent(s), Acceptable

0,00



Bonnet, Repaired, P - Check

0,00



Door F L, Scratch(es), Acceptable 0,00



Alloy rim R L, Scratch(es), Acceptable 0,00



Alloy rim F R, Scratch(es), Acceptable 0,00



Alloy rim R R, Scratch(es), Acceptable 0,00

