


**PEUGEOT 308 SW: 1LSN364**

Vinnumber:	<b>VF3LCBHY8FS307515</b>	Versionname:	<b>1.6 BLUEHDI 73KW S/S ACTIVE</b>
First Registrationdate:	<b>24/11/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>1</b>	Power Kw:	<b>73</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>NOT OK</b>
Battery functioning:	<b>No</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>NOT OK</b>		
Registration Certificate Car (BE):	<b>No</b>		

**Options**

GPS storage		Central consol F	
GPS storage	<b>HD</b>	Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>Tow bar removable</b>
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>NOT OK</b>	Battery functioning	<b>No</b>
Tires wear profile	<b>OK</b>	Power steering	<b>No</b>
Idle position	<b>NOT OK</b>	Sound engine	<b>NOT OK</b>
Engine startingtime	<b>NOT OK</b>	Clutch test	<b>NOT OK</b>
Exhaust gass	<b>NOT OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>NOT OK</b>
		Lighting	<b>NOT OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/55/16/91 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 7 mm</b>	Fr.R.	<b>Michelin: 7 mm</b>
	Re.L.	<b>Goodyear: 8 mm</b>	Re.R.	<b>Goodyear: 8 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Total cost ex VAT			<b>957,50</b>
Roof, Dent(s), PDR - Paintless dent repair			<b>63,00</b>



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Sill outer L, Dent(s) and scratch(es), LI - Repair and paint (complete) 454,50



Ignition key, Missing, E - Replace 150,00



Interior, Dirty, Cleaning 100,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



