


RENAULT CLIO: 1NEJ871

Vinnumber:	VF15R0J0A54118312	Versionname:	1.5 ENERGY DCI 90E EXPRESSION
First Registrationdate:	4/02/2016	Fiscalpower:	
Expertise Mileage:	116648	Power Kw:	66
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4227
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/65/15/92 V Steel			
Winter tyres:	Fr.L.	Michelin: 2 mm	Fr.R.	Michelin: 2 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1434,62
Rear window, Scratch(es), E - Replace	320,00



Wing R L, Dent(s), Acceptable 0,00

No pictures to display

Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R L, Scratch(es), Acceptable 0,00

No pictures to display

Aerial, Deformed / Strained, E - Replace 12,00



Engine protective plate, Deformed / Strained, E - Replace 75,00



Wing F L, Scratch(es), LI - Repair and paint (complete) 176,14



Rocker panel inner R L, Dent(s), LI - Repair and paint (complete) 115,56



Door F L, Scratch(es), LI - Repair and paint (complete) 254,68



Door R L, Dent(s), Acceptable 0,00

No pictures to display

Roof, Dent(s), PDR - Paintless dent repair 63,00



Bumper corner R R, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R R, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete) 115,56



Door R R, Dent(s), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F L, Broken, E - Replace 24,00



Ignition key, Missing, E - Replace 0,00



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 254,68



Wheel cover F R, Scratch(es), E - Replace 24,00



Bonnet, Bad repair, Acceptable 0,00

No pictures to display