



MERCEDES CLA SHOOTING BRAKE: 1LFR339

Vinnumber:	WDD1179081N183344	Versionname:	2.1 CLA 200 D URBAN SHOOTING BRAKE
First Registrationdate:	15/09/2015	Fiscalpower:	
Expertise Mileage:	193536	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3616
Number of doors:	5		
Number of seats:	5		
Number head rests:	1		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage	SD	Central consol F	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar fixed
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/40/18/92 Y LightMetal				
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Repair kit	No	Compressor	No
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT **2337,98**

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) **95,00**



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Sill outer R, Scratch(es), 67 - Polish

0,00

No pictures to display

Tyre repair kit, Missing, E - Replace

210,53



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Windscreen, Stone chip(s), Windscreen repair 0,00



Roof, Scratch(es), 67 - Polish 0,00

No pictures to display

Luggage space cover, Missing, E - Replace 240,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Seat cover F L, Worn, Acceptable 0,00



Compressor, Missing, E - Replace 0,00



Door F R, Dent(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper grille, Broken, E - Replace	32,40



Wing R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	308,20



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------

