



OPEL Movano 3500 MWB Med.High Roof: 1CRH298

Vinnumber:	WOLMRF4DCAB021930	Versionname:	MOVANO 3500 B/F MWB L2H2 (E5) DPF 125PK
First Registrationdate:	8/02/2012	Fiscalpower:	
Expertise Mileage:	203612	Power Kw:	92
Bodytype:		Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	TRU15
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD		Rear parking sensors
Windows electric F		
Type of headlighting	Headlighting Halogen	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/65/16/92 MS Steel			
Winter tyres:	Fr.L.	Other: 3 mm	Fr.R.	Other: 3 mm
	Re.L.	Other: 4 mm	Re.R.	Other: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1633,93
-------------------	---------

Bumper R, Crack, E - Replace	329,40
------------------------------	--------



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	238,76
---	--------



Ignition key, Missing, E - Replace 150,00

No pictures to display

Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover F L, Damaged, E - Replace 300,00



Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Dent(s), LI - Repair and paint (complete) 505,13



Bumper F, Scratch(es), Smart repair 110,64



Door F L, Dent(s), Acceptable 0,00

No pictures to display