



MERCEDES CLA SHOOTING BRAKE: 1PTY116

Vinnumber:	WDD1179081N435701	Versionname:	2.1 CLA 200 D URBAN SHOOTING BRAKE
First Registrationdate:	19/09/2016	Fiscalpower:	
Expertise Mileage:	173602	Power Kw:	100
Bodytype:		Body color	Silver
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	4311
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F
GPS storage	SD	Luggage cover
GPS storage		
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting LED	
Type of GPS	GPS big screen color	
Type of Lining	Lining semi-artificial leather	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/40/18/92 MS LightMetal			
Winter tyres:	Fr.L.	Fulda: 5 mm	Fr.R.	Fulda: 5 mm
	Re.L.	Fulda: 6 mm	Re.R.	Fulda: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	700,75
Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)	95,00



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00




Bumper F L, Scratch(es), It - Spot repair 115,56



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Rear window, Scratch(es), 67 - Polish 55,19



Certificate Of Conformity, Missing, E - Replace 150,00

No pictures to display

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Seat cover F L, Damaged, Acceptable 0,00

