



PEUGEOT Partner: 1EPS423

Vinnumber:	VF37A9HN0CN543437	Versionname:	PARTNER B/F L1H1 Conf.120 75PK
First Registrationdate:	18/02/2013	Fiscalpower:	
Expertise Mileage:	89236	Power Kw:	55
Bodytype:		Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	1510
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Type of headlighting	Headlighting Halogen		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 T Steel			
Winter tyres:	Fr.L.	Fulda: 8 mm	Fr.R.	Fulda: 8 mm
	Re.L.	Fulda: 8 mm	Re.R.	Fulda: 8 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1931,21
-------------------	----------------

Ignition key, Missing, E - Replace	150,00
------------------------------------	---------------

No pictures to display

Trunk door R L, Deformed / Strained, LI - Repair and paint (partial)	200,00
--	---------------



Door trim R R, Scratch(es), E - Replace	91,50
---	--------------



Interior, Damaged, Acceptable 0,00



Bumper R, Deformed / Strained, E - Replace 329,40



Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 165,13



Roof, Dent(s), LI - Repair and paint (complete) 361,13



Bumper F, Deformed / Strained, Le - Replace and paint 575,25



Windscreen, Stone chip(s), Windscreen repair 58,80

