



VOLVO V40: 1NJR958

Vinnumber:	VV1MV74L1G2330372	Versionname:	2.0 D2 KINETIC
First Registrationdate:	4/03/2016	Fiscalpower:	
Expertise Mileage:	68036	Power Kw:	88
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4531
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	931,95
-------------------	---------------

Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	---------------



Roof pillar R, Chemical polution, Acceptable 0,00



Door R R, Scratch(es), Acceptable 0,00



Rear spoiler, Chemical polution, Acceptable 0,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Door R L, Scratch(es), Acceptable 0,00



Door frame F L, Scratch(es), Acceptable 0,00



Roof, Chemical polution, Acceptable 0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door F L, Bad repair, LI - Repair and paint (complete)

318,35



Wing R L, Scratch(es), Acceptable

0,00



Wing R R, Chemical polution, Acceptable

0,00



Mirror side blinker R, Scratch(es), Acceptable

0,00



Alloy rim R R, Scratch(es), Acceptable

0,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80

