


LU Volkswagen Polo: EM5961

Vinnnumber:	WVWZZZ6RZGY076225	Versionname:	1.4 TDI DSG 66KW COMFORTLINE BMT
First Registrationdate:	8/10/2015	Fiscalpower:	
Expertise Mileage:	46866	Power Kw:	66
Bodytype:		Body color:	Silver
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	2808
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	
Windows electric R	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/60/15/92 MS Steel			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Total cost ex VAT			190,00
Ignition key, Missing, E - Replace			150,00
<i>No pictures to display</i>			
Wing R R, Repaired, Acceptable			0,00
<i>No pictures to display</i>			
Boot cover, Missing, E - Replace			40,00



Maintenance, Maintenance, Execute

0,00

No pictures to display