


BMW 3 BERLINE: 1PFN633

| | | | |
|------------------------------------|--------------------------|--------------|---------------------------------|
| Vinnumber: | WBA8C31060K804377 | Versionname: | 2.0 318D (110KW) BERLINE |
| First Registrationdate: | 23/06/2016 | Fiscalpower: | |
| Expertise Mileage: | 136247 | Power Kw: | 110 |
| Bodytype: | | Body color: | Brown |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Back | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 4226 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|------------------------------|
| Radio CD | Central consol F |
| Windows electric F | Luggage cover |
| Windows electric R | Front parking sensors |
| Cruise Control | Rear parking sensors |
| Steering wheel multifunctional | Type of Tow bar |
| Radio multimedia | No Tow bar |
| Type of headlighting | Headlighting LED |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining fabrics |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|----------------------|-------|----------------------|
| | 205/60/16/92 V LightMetal | | | |
| Summer tyres: | Fr.L. | Pirelli: 3 mm | Fr.R. | Pirelli: 3 mm |
| | Re.L. | Pirelli: 3 mm | Re.R. | Pirelli: 3 mm |

Assistance equipment

| | | | |
|--|----------|--|-------------|
| Number of charging cables (normal) | 0 | | |
| Number of charging cables (rapid charge) | 0 | | |
| Total cost ex VAT | | | 0,00 |
| Door FR, Scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Bumper R, Scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Alloy rim RL, Scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Tailgate, Scratch(es), Acceptable | | | 0,00 |

| | |
|-------------------------------|------|
| Tailgate, Dent(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Roof, Dent(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |