



FORD S-MAX: 1SKH011

Vinnumber:	WFOJXXWPCJHM02846	Versionname:	2.0 TDCi 4x4 132kW S/S PS Busin. Class+
First Registrationdate:	30/05/2017	Fiscalpower:	
Expertise Mileage:	76481	Power Kw:	132
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3327
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage	HD	Seats electric F R	
GPS storage		Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	Tow bar fixed
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

235/55/17/103 V LightMetal				
Winter tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1679,02
-------------------	----------------

Luggage compartment cover, Missing, E - Replace	288,00
-------------------------------------------------	---------------



Door FL, Scratch(es), Acceptable 0,00

No pictures to display

Internal boot lining R, Scratch(es), Smart repair 110,64



Bodywork, Chemical polution, Acceptable 0,00

No pictures to display

Alloy rim FR, Scratch(es), LI - Repair and paint (complete) 95,00



Rear bulkhead lining, Missing, E - Replace 75,00



Mirror side repeater L, Broken, E - Replace 31,20



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Wing RR, Scratch(es), Acceptable 0,00

No pictures to display

Spoiler FR, Scratch(es), E - Replace 48,00



Interior, Dirty, Chemical cleaning 125,00



Alloy rim FL, Scratch(es), Acceptable 0,00

No pictures to display

Door RR, Repaired, Acceptable 0,00



Outside rear-view mirror housing L, Scratch(es), LI - Repair and paint (complete) 75,00



Door FR, Dent(s) and scratch(es), LI - Repair and paint (complete) 430,02



Door RL, Scratch(es), Acceptable 0,00

No pictures to display

Spoiler R, Deformed / Strained, E - Replace 99,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 302,16



Rear window, Scratch(es), E - Replace 0,00

