



AUDI A4 AVANT: 1JSJ861

Vinnumber:	WAUZZZ8K6FA092903	Versionname:	2.0 TDI ULTRA
First Registrationdate:	13/02/2015	Fiscalpower:	
Expertise Mileage:	64486	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	IN 16000 KM	Parking lot:	2326
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric
GPS storage		Panoramic roof
GPS storage	DVD	Central consol F
Windows electric F		Luggage cover
Windows electric R		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 H LightMetal			
Winter tyres:	Fr.L.	Kleber: 7 mm	Fr.R.	Kleber: 7 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1103,68
--------------------------	----------------

Alloy rim FR, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------



Alloy rim RR, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim FL, Scratch(es), Acceptable 0,00

No pictures to display

Outer sill R, Dent(s), LI - Repair and paint (complete) 382,50



Windscreen, Stone chip(s), Windscreen repair 58,80



Xenon headlight L, Scratch(es), Acceptable 0,00

No pictures to display

Boot carpet, Dirty, Cleaning 25,00



Door RL, Scratch(es), Acceptable 0,00

No pictures to display

Outer door handle FR, Scratch(es), LI - Repair and paint (complete) 115,56



Wing FL, Dent(s) and scratch(es), LI - Repair and paint (complete) 316,18



Boot lid covering R, Scratch(es), Smart repair 110,64

