



**AUDI A3 BERLINE: 1RTE471**

Vinnumber:	<b>WAUZZZ8V1H1058056</b>	Versionname:	<b>1.6 TDi 81kW</b>
First Registrationdate:	<b>23/02/2017</b>	Fiscalpower:	
Expertise Mileage:	<b>80090</b>	Power Kw:	<b>81</b>
Bodytype:		Body color:	<b>Dark Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1404</b>
Number of doors:	<b>4</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

GPS storage		Central consol F
GPS storage	<b>SD</b>	Luggage cover
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	<b>Headlighting LED</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/55/16/91 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Goodyear: 8 mm</b>	Fr.R.	<b>Goodyear: 8 mm</b>
	Re.L.	<b>Goodyear: 8 mm</b>	Re.R.	<b>Goodyear: 8 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	1491,50
Bumper grille, Broken, E - Replace	32,40





Roof, Chemical polution, LI - Repair and paint (complete) 481,50



Door FL, Dent(s), PDR - Paintless dent repair 63,00



Alloy rim FR, Scratch(es), LI - Repair and paint (complete) 95,00



Roof pillar R, Chemical polution, Acceptable 0,00

No pictures to display

Tailgate, Chemical polution, Acceptable 0,00

No pictures to display

Alloy rim RR, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim FL, Scratch(es), LI - Repair and paint (complete) 95,00



Door RR, Dent(s), PDR - Paintless dent repair 63,00



Alloy rim RL, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

259,80



Bonnet, Bad repair, LI - Repair and paint (complete)

0,00

