



**BMW 4 GRAN COUPE: SR8974**

|                                    |                          |              |                                    |
|------------------------------------|--------------------------|--------------|------------------------------------|
| Vinnumber:                         | <b>WBA4E91010G391413</b> | Versionname: | <b>2.0 420D (140KW) GRAN COUPE</b> |
| First Registrationdate:            | <b>29/02/2016</b>        | Fiscalpower: |                                    |
| Expertise Mileage:                 | <b>192937</b>            | Power Kw:    | <b>140</b>                         |
| Bodytype:                          |                          | Body color:  | <b>Grey</b>                        |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                     |
| Transmission:                      | <b>Back</b>              | Rims summer: | <b>Aluminium</b>                   |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                          |
| Maintenance:                       | <b>OK</b>                | Parking lot: | <b>2424</b>                        |
| Battery functioning:               | <b>Yes</b>               |              |                                    |
| Number of doors:                   | <b>5</b>                 |              |                                    |
| Number of seats:                   | <b>5</b>                 |              |                                    |
| Number head rests:                 | <b>4</b>                 |              |                                    |
| Rims summer:                       | <b>Aluminium</b>         |              |                                    |
| Category:                          | <b>Passenger Car</b>     |              |                                    |
| Oil level:                         | <b>OK</b>                |              |                                    |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                    |

**Options**

|                                |                                  |
|--------------------------------|----------------------------------|
| Radio CD                       | Central consol F                 |
| Windows electric F             | Luggage cover                    |
| Windows electric R             | Front parking sensors            |
| Cruise Control                 | Rear parking sensors             |
| Steering wheel multifunctional |                                  |
| Type of headlighting           | <b>Headlighting Xenon</b>        |
| Type of GPS                    | <b>GPS big screen color</b>      |
| Type of Lining                 | <b>Lining artificial leather</b> |
| Type of climate control        | <b>Autom climate control</b>     |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                   |       |                      |       |                      |
|-----------------------------------|-------|----------------------|-------|----------------------|
| <b>225/50/17/92 MS LightMetal</b> |       |                      |       |                      |
| Winter tyres:                     | Fr.L. | <b>Pirelli: 4 mm</b> | Fr.R. | <b>Pirelli: 4 mm</b> |
|                                   | Re.L. | <b>Pirelli: 5 mm</b> | Re.R. | <b>Pirelli: 5 mm</b> |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|                                    |               |
|------------------------------------|---------------|
| Total cost ex VAT                  | <b>659,77</b> |
| Handbrake cover, Tear, E - Replace | <b>62,00</b>  |



Tailgate, Chemical polution, 67 - Polish

0,00



Door FR, Dent(s), PDR - Paintless dent repair

63,00



Boot cover, Scratch(es), E - Replace

60,00



Alloy rim RR, Scratch(es), LI - Repair and paint (complete)

95,00



Wing FL, Dent(s), LI - Repair and paint (complete)

264,21



Bumper FR, Scratch(es), It - Spot repair

115,56

