



AUDI A6 AVANT: 1NJ421

Vinnumber:	WAUZZZ4G3GN152485	Versionname:	2.0 TDI ULTRA 110KW S TRONIC
First Registrationdate:	3/03/2016	Fiscalpower:	
Expertise Mileage:	161484	Power Kw:	110
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2533
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric	
GPS storage		Panoramic roof	
GPS storage	HD	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar fixed
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/55/17/97 H LightMetal				
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1141,37
Alloy rim RL, Scratch(es), LI - Repair and paint (complete)	95,00



Wing FR, Scratch(es), LI - Repair and paint (complete)

264,21



Floor covering FL, Hole, Smart repair

64,32



Wing RR, Dent(s) and scratch(es), LI - Repair and paint (complete)

369,84



Alloy rim RR, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Wing RL, Dent(s), PDR - Paintless dent repair

63,00



Bumper F, Bad repair, Acceptable

0,00





Door FR, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim FR, Scratch(es), LI - Repair and paint (complete) 95,00



Door FL, Scratch(es), Acceptable 0,00

No pictures to display

Windscreen, Stone chip(s), Acceptable 0,00



Alloy rim FL, Scratch(es), LI - Repair and paint (complete) 95,00



Door RL, Scratch(es), Acceptable 0,00

No pictures to display

Door RR, Scratch(es), Acceptable 0,00

No pictures to display