



AUDI A3: 1HDP243

Vinnumber:	WAUZZZ8V6FA004619	Versionname:	A3 SB Ultra Attraction 110PK
First Registrationdate:	25/06/2014	Fiscalpower:	
Expertise Mileage:	129407	Power Kw:	81
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	3613
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	NOT OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	NOT OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	613,60
-------------------	---------------

Wing RL, Scratch(es), Acceptable	0,00
----------------------------------	-------------

No pictures to display

Service, Maintenance, Execute	0,00
-------------------------------	-------------

No pictures to display

Wing FR, Chemical polution, Acceptable	0,00
--	-------------

No pictures to display

No pictures to display

Outside rear-view mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim FR, Scratch(es), Acceptable 0,00

No pictures to display

Door RR, Chemical polution, Acceptable 0,00

No pictures to display

Door RL, Chemical polution, Acceptable 0,00

No pictures to display

Door FR, Chemical polution, Acceptable 0,00

No pictures to display

Door FL, Chemical polution, Acceptable 0,00

No pictures to display

Bumper F, Crack, LI - Repair and paint (complete) 211,80



Alloy rim RR, Scratch(es), LI - Repair and paint (complete) 95,00



Roof, Chemical polution, Acceptable 0,00

No pictures to display

Outside rear-view mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Chemical polution, Acceptable 0,00

No pictures to display

Alloy rim RL, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80

