



**VOLVO V60: 1KXB805**

Vinnumber:	<b>YV1FW74C1G1294397</b>	Versionname:	<b>2.0 D2 KINETIC</b>
First Registrationdate:	<b>20/07/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>170813</b>	Power Kw:	<b>88</b>
Bodytype:		Body color:	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1723</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Rear parking sensors	
Windows electric F		Type of Tow bar	<b>No Tow bar</b>
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>215/55/16/93 H LightMetal</b>				
Winter tyres:	Fr.L.	<b>Dunlop: 6 mm</b>	Fr.R.	<b>Dunlop: 6 mm</b>
	Re.L.	<b>Dunlop: 5 mm</b>	Re.R.	<b>Dunlop: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>675,15</b>
-------------------	---------------

Interior, Stain, Cleaning	<b>50,00</b>
---------------------------	--------------



Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim FR, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim FL, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim RR, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Windscreen, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Wing RR, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Door RR, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35



Door RL, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Tyre RR, Flat, Acceptable	0,00



Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Alloy rim RL, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Engine, Not functioning (well), P - Check	0,00
---	------

