


BMW 1 HATCH: 1JNF792

Vinnumber:	WBA1C91060P875960	Versionname:	1.6 116D EFFICIENTDYNAMICS EDIT. (85KW)
First Registrationdate:	23/01/2015	Fiscalpower:	
Expertise Mileage:	48530	Power Kw:	85
Bodytype:	Hatchback	Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1526
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Seats F heated	No Tow bar
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 T LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	190,00
Door RL, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim FL, Scratch(es), LI - Repair and paint (complete)	95,00



Outside rear-view mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim FR, Scratch(es), LI - Repair and paint (complete) 95,00



Boot lid covering R, Scratch(es), Acceptable 0,00

No pictures to display

Wing RR, Scratch(es), Acceptable 0,00

No pictures to display

Bumper FL, Scratch(es), Acceptable 0,00

No pictures to display

Rear window, Not original part, Acceptable 0,00

No pictures to display