



**VOLVO V40: 1REZ034**

Vinnumber:	<b>VV1MV74L1H2407952</b>	Versionname:	<b>2.0 D2 KINETIC</b>
First Registrationdate:	<b>5/12/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>69031</b>	Power Kw:	<b>88</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance	<b>PLUS 28005 KM</b>	Parking lot:	<b>2413</b>
Maintenance	<b>OK</b>		
Battery functioning	<b>Yes</b>		
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>HD</b>	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	<b>No Tow bar</b>
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/55/16/91 T LightMetal</b>				
Winter tyres:	Fr.L.	<b>Pirelli: 4 mm</b>	Fr.R.	<b>Pirelli: 4 mm</b>
	Re.L.	<b>Pirelli: 3 mm</b>	Re.R.	<b>Pirelli: 3 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>285,00</b>
Wing FL, Repaired, No repair	<b>0,00</b>



Alloy rim FR, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper FL, Scratch(es), Acceptable 0,00



Alloy rim RL, Scratch(es), LI - Repair and paint (complete) 95,00



Outside rear-view mirror housing R, Scratch(es), Acceptable 0,00



Door panel RR, Scratch(es), Acceptable 0,00



Bumper R, Scratch(es), Acceptable 0,00



Door FR, Scratch(es), Acceptable 0,00



Alloy rim FL, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim FR, Scratch(es), LI - Repair and paint (complete) 95,00