



FORD MONDEOO: 1THN802

Vinnumber:	WFOFXWPCFHK53235	Versionname:	
First Registrationdate:	9/11/2017	Fiscalpower:	
Expertise Mileage:	167423	Power Kw:	88
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2112
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar fixed
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/92 MS LightMetal			
Winter tyres:	Fr.L.	Fulda: 4 mm	Fr.R.	Fulda: 4 mm
	Re.L.	Fulda: 5 mm	Re.R.	Fulda: 5 mm










Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT 2394,18

Wing FR, Scratch(es), LI - Repair and paint (complete) 0,00



Door RR, Scratch(es), LI - Repair and paint (complete)	0,00
	
Bonnet, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Tailgate, Scratch(es), LI - Repair and paint (complete)	301,68
	
Door FR, Scratch(es), LI - Repair and paint (complete)	318,35
	
Door FL, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Wing RR, Scratch(es), LI - Repair and paint (complete)	0,00
	
Boot lid covering R, Scratch(es), Smart repair	110,64
	
Wing RL, Scratch(es), LI - Repair and paint (complete)	0,00
	
Outer sill R, Scratch(es), LI - Repair and paint (complete)	0,00
	
Ignition key, Missing, E - Replace	150,00
<i>No pictures to display</i>	
Outside rear-view mirror housing R, Scratch(es), LI - Repair and paint (complete)	115,56
	
Door RL, Scratch(es), LI - Repair and paint (complete)	318,35
	
Door panel FR, Tear, E - Replace	114,00



Windscreen, Scratch(es), E - Replace 0,00



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 259,80



Interior, Dirty, Cleaning 0,00



Roof liner, Tear, E - Replace 494,00

