



AUDI Q5: 1NGP403

Vinnumber:	WAUZZZ8RXGA097259	Versionname:	2.0 TDI 110KW
First Registrationdate:	19/02/2016	Fiscalpower:	
Expertise Mileage:	125183	Power Kw:	110
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Rims summer:	Aluminium
Transmission:	Front	Oil level:	OK
Fueltype:	Diesel	Parking lot:	3309
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage		Seats electric F R	
GPS storage	HD	Sun Roof electric	
Windows electric F		Panoramic roof	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

235/65/17/104 H LightMetal				
Winter tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT 1345,03

Alloy rim RL, Scratch(es), Acceptable 0,00

No pictures to display

Ignition key, Missing, E - Replace 360,00

No pictures to display

Alloy rim FR, Scratch(es), Acceptable 0,00

No pictures to display

Wing FL, Dent(s) and scratch(es), LI - Repair and paint (complete) 375,05



Inner door sill RL, Scratch(es), Acceptable 0,00

No pictures to display

Door RL, Scratch(es), Acceptable 0,00

No pictures to display

Door FR, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim FL, Scratch(es), Acceptable 0,00

No pictures to display

Tyre RR, Tear, Acceptable 0,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 304,99



Wing FR, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 304,99

