


FORD MONDEO CLIPPER: 1LGZ314

Vinnumber:	WF0FXXWPCFEA28977	Versionname:	2.0 TDCI 110KW S/S ECONETIC BUSINESS ED+
First Registrationdate:	25/09/2015	Fiscalpower:	
Expertise Mileage:	180945	Power Kw:	110
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1532
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F		Seats electric F L	
Windows electric R		Seats electric F R	
Cruise Control		Central consol F	
Steering wheel multifunctional		Luggage cover	
Seats F heated		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting Halogen	Type of Tow bar	Tow bar removable
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/99 H LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 4 mm	Fr.R.	Uniroyal: 4 mm
	Re.L.	Uniroyal: 4 mm	Re.R.	Uniroyal: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1073,80
Alloy rim FR, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Boot lid covering R, Scratch(es), Smart repair	110,64



Door RR, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Bumper R, Dent(s), LI - Repair and paint (complete) 211,80



Ignition key, Missing, E - Replace 150,00

No pictures to display

Internal boot lining R, Scratch(es), Smart repair 110,64



Door FL, Scratch(es), Acceptable 0,00

No pictures to display

Internal boot lining L, Scratch(es), Smart repair 110,64



Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete) 301,68



Reflector, Scratch(es), E - Replace 64,00



Wing RR, Scratch(es), Acceptable 0,00

No pictures to display

Bumper moulding FL, Broken, E - Replace 14,40



Door RL, Scratch(es), Acceptable 0,00

No pictures to display