



**MERCEDES A: 1NGU334**

Vinnumber:	<b>WDD1760111V137770</b>	Versionname:	<b>1.5 A 160 D URBAN</b>
First Registrationdate:	<b>22/02/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>124403</b>	Power Kw:	<b>66</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1332</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>1</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD Type of Tow bar
Windows electric F	<b>No Tow bar</b>
Windows electric R	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting LED</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining semi-leather</b>
Type of climate control	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>225/40/18/92 V LightMetal</b>				
Summer tyres:	Fr.L.	<b>Michelin: 6 mm</b>	Fr.R.	<b>Michelin: 6 mm</b>
	Re.L.	<b>Michelin: 7 mm</b>	Re.R.	<b>Michelin: 7 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			<b>663,60</b>
Bodywork, Not original part, Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Rear window, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Alloy rim FR polished, Scratch(es), LI - Repair and paint (complete)			<b>95,00</b>



Alloy rim RL polished, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim FL polished, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Stain, Cleaning 50,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Outside rear-view mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim RR polished, Scratch(es), LI - Repair and paint (complete) 95,00

