


BMW X5: 1NGZ456

Vinnumber:	WBAKT410100K97945	Versionname:	2.0 SDRIVE25D (155KW) AUTO
First Registrationdate:	23/02/2016	Fiscalpower:	
Expertise Mileage:	181200	Power Kw:	155
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2207
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage	HD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar fixed
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	255/55/18/109 V LightMetal			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT 1109,34

Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Outside rear-view mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Door RR, Dent(s), Acceptable 0,00

No pictures to display

Wing RR, Dent(s), PDR - Paintless dent repair

63,00



Door RL, Scratch(es), LI - Repair and paint (complete)

382,02



Bumper F, Scratch(es), LI - Repair and paint (complete)

254,16



Floot mat(s), Hole, Acceptable

0,00

No pictures to display

Fog lamp L, Broken, E - Replace

156,00



Bumper R, Crack, LI - Repair and paint (complete)

254,16



Seat cover FL, Worn, Acceptable

0,00

No pictures to display

Wing FR, Scratch(es), Acceptable

0,00

No pictures to display